(continuation sheet)

Hole Number: 50MW18

Project: VAFB Site 50

Geologist: C. Rohlfing

Sheet 2 of 2 Sheets

Elev (ft)	Depth (ft) bgs	Recovery (ft)	Description of Materials	USCS/ Litho	Field PID Results	Geotech. Sample or Core Box No.	Analytical Sample	Remarks
			Sandy silt - greenish gray to dark brown; 60% silt; 40% fine to medium sand, subangular to round; moist; no odor.	ML/SDSL				
	5		Sandy clay - tan to greenish gray; 65% medium plasticity clay; 35% fine sand, subangular to subround; loose; moist; no odor.	CL/SDCL				
	10		at 12': Poorly graded sand - greenish gray to gray; 60% fine sand, 40% medium sand, subangular to round; minor silt; micaceous; dry; medium dense; no odor.	SP/SD				
	15		as above	SP/SD				
	20		as above	SP/SD				
	25		as above	SP/SD				groundwater at app. 25 feet bgs
			at 26': Sandy clay - greenish gray; 90% low plasticity clay; 10% fine sand, moist; hard; no odor.	CL/SDCL				
	30		at 26.5': Poorly graded sand - greenish gray to gray; 60% fine sand, 40% medium sand, subangular to round; moist; very dense; no odor.	SP/SD				
			as above	SP/SD				
	35		as above	SP/SD				
	40		as above	SP/SD				
			at 43': bedrock: Sandy clay with gravel - greenish gray; 80% stiff, medium plasticity clay; 10% fine to medium sand, subangular to round; 10% fine to medium gravel, angular to round; shaley texture; dry; very dense; no odor.	CL/CLSN				
	45							
			Total depth = 46 feet bgs					
	50							

Project VAFB Site 50