Hole Number: 156MW14

Project: VAFB Site 50

Geologist: C. Rohling

Sheet 1

Elev (ft)	Depth (ft) bgs	Recovery (ft)	Description of Materials	USCS/ Litho	Field PID Results	Geotech. Sample or Core Box No.	Analytical Sample No.	Remarks
			Silty sand - light brown to dark brown; 80% fine to medium sand, subangular to subround; 20% silt; minor fine gravel; angular to round; dry; no odor.	SM/SDSL				
	5		Sandy clay - brown to dark brown; 65% fine to medium sand, subangular to subround; 35% low plasticity clay; minor fine gravel; subround to round; moist; medium dense; no odor.	SC/SDCL				
	10		Poorly graded sand - greenish gray to gray; 70% fine sand, 30% medium sand, subangular to round; micaceous; moist; very dense; no odor.	SP/SD				groundwater at app. 11 feet bgs
			at 13': Sandy clay - greenish gray to gray; 90% stiff, medium plasticity clay; 10% fine sand, subangular to subround; moist; firm; no odor.	CL/SDCL				
	15							
			Same as above					
	20		Total Depth 20 feet.					
	25							
	30							
	35							
	40							
	45							
	50							

Project VAFB Site 50