(continuation sheet)

Hole Number: 50MW17

Project: VAFB Site 50

Geologist: C. Rohlfing

Sheet 2 of 2 Sheets

Elev (ft)	Depth (ft) bgs	Recovery (ft)	Description of Materials	USCS/ Litho	Field PID Results	Geotech. Sample or Core Box No.	Analytical Sample	Remarks
			Poorly graded sand with silt - buff to brown; 90% fine to medium sand, subangular to round; 10% silt; minor fine gravel; subangular to round; micaceous; dry; no odor.	SP/SDSL				
	5		Poorly graded sand - yellow brown; 70% fine sand, 30% medium sand, subangular to round; minor silt; dry; medium dense; no odor.	SP/SD				
	10		Silty sand - gray to orange brown; 70% fine to coarse sand, subangular to round; 30% silt; micaceous; moist; medium dense; no odor.	SM/SDSL				groundwater at app. 12 feet bgs
	15		clayey sand with gravel - chalk to gray; 60% fine to coarse sand, subangular to round; 30% low plasticity clay; 10% fine gravel; subangular to round; micaceous; saturated; medium dense; no odor.	SC/SDCL				
			at 18': Sandy clay - gray to brown; 90% stiff, medium plasticity clay; 10% fine sand, subangular to round; moist; firm; no odor.	CL/SDCL				
	20		as above	CL/SDCL				
			Total depth = 22 feet bgs					
	25							
	30							
	35							
	40							
	45							
	50							

Project VAFB Site 50