(continuation sheet)

Hole Number: 156MW9

Project: VAFB Site 50

Geologist: C. Rohlfing

Sheet 2 of 2 Sheets

Elev (ft)	Depth (ft) bgs	Recovery (ft)	Description of Materials	USCS/ Litho	Field PID Results	Geotech. Sample or Core Box No.	Analytical Sample	Remarks
			Silty sand with gravel - dark brown to black; 70% fine to medium sand, subangular to round; 20% silt; 10% fine gravel, subround to round; micaceous; moist; no odor.	SM/SDSL				
	5		Silty sand - yellow brown to gray; 60% fine to medium sand, subangular to subround; 40% silt; minor fine gravel, subangular to round; micaceous; micaceous; very dense; dry; no odor.	SM/SDSL				
	10		Poorly graded sand - gray to greenish gray; 60% fine sand, 40% medium sand, subangular to round; micaceous; moist; very dense; no odor.	SP/SD				groundwater at app. 10 feet bgs
			at 13.5': Sandy clay - greenish gray; 90% stiff, medium plasticity clay; 10% fine sand, subangular to subround; dry; firm; no odor.	CL/SDCL				
	15		Total depth = 15 feet bgs					
	20							
	25							
	30							
	35							
	40							
	45							
	50							

Project VAFB Site 50