(continuation sheet)

Hole Number: 50MW19

Project: VAFB Site 50

Geologist: C. Rohlfing

Sheet 2 of 2 Sheets

Elev (ft)	Depth (ft) bgs	Recovery (ft)	Description of Materials	USCS/ Litho	Field PID Results	Geotech. Sample or Core Box No.	Analytical Sample	Remarks
			Silty sand - dark brown to black; 75% fine sand, subangular to subround 25% silt; minor fine gravel; micaceous; moist; no odor.	SM/SDSL				
	5		Sandy silt - black; 60% silt; 40% fine sand, subangular to subround; loose moist; no odor.	ML/SDSL				
	10		Clayey sand - gray with reddish brown mottling; 60% fine to medium sand, subangular to subround; 40% low plasticity clay; medium dense; moist; no odor.	SC/SDCL				groundwater at app. 12 feet bgs
	15		at 16': Sandy clay - chalk to gray; 85% stiff, medium plasticity clay; 15% fine sand, subangular to subround; soft; dry; no odor.	CL/SDCL				
	20		as above	CL/SDCL				
			as above	CL/SDCL				
	25		Total depth = 24 feet bgs					
	30							
	35							
	40							
	45							
	50							

Project VAFB Site 50