(continuation sheet)

Hole Number: 156MW1

Project: VAFB Site 50

Geologist: C. Rohlfing

Sheet 2 of 2 Sheets

Elev (ft)	Depth (ft)	Recovery (ft)	Description of Materials	USCS/ Litho	Field PID Results	Geotech. Sample or Core Box No.	Analytical Sample	Remarks
			From cuttings:					
			Sandy Silt - dark brown to reddish brown; 60% silt; 30% fine sand; 10% medium sand; subangular to subround; moist, no hydrocarbon odor.	ML/SDSL	<10			
	5		Silty Sand - yellowish brown to reddish brown; 70% fine sand; 10% medium sand; subangular to round; 20% silt; moist; no hydrocarbon odor.	SM/SDSL	<10			
	10		Poorly graded sand - olive; 60% fine sand; 40% medium sand; subangular to round; calcite veinlets; moist; no hydrocarbon odor.	SP/SD	<10			
	15		Clayey Sand - chalk to olive with reddish brown mottling; 70% fine sand; subangular to subround; 30% low plasticity clay; moist; no hydrocarbon odor.	SC/SDCL	<10			Groundwater encountered at app. 18 feet bgs
	2		Sandy Clay - chalk to olive; 60% medium plasticity clay; 40% fine sand; subangular to subround; moist; no hydrocarbon odor.	CL/SDCL	<10			
	2		as above Total depth = 25 feet bgs	CL/SDCL	<10			
	3							
	3							
	4							
	4							
	5							

Project: VAFB Site 50, AOC156