

LEGEND

- GROUNDWATER MONITORING WELL
- DESTROYED GROUNDWATER MONITORING WELL
- GROUNDWATER EXTRACTION WELL

NORTH

0 40 80

SCALE IN FEET

NOTE: SITE MAP ADAPTED FROM SECOR INTERNATIONAL FIGURES.
SITE DIMESIONS AND FACILITY LOCATIONS NOT VERIFIED.

URS

Project No. 38486366

ARCO Service Station 0716
699 San Antonio Road
Palo Alto, California

SITE MAP

X:\x_env_waste\BP GEM\Sites\Sites-PDF\00716.dwg, 12/05/2003 11:11:07 AM, JKMT, URS