

EXPLANATION

MW-1 *MONITORING WELL LOCATION AND DESIGNATION*

FORMER UST LOCATION

1"=30'

BLUE LAKE BELTING AND LEATHER WORKS
BLUE LAKE, CALIFORINA

SITE MAP SHOWING SOIL BORING AND MONITORING WELL LOCATIONS

SHN 097309
MARCH, 2002
FIGURE 1

097309-GEOTRACK