

FN 21010003

ERI ENVIRONMENTAL RESOLUTIONS, INC.

GROUNDWATER ELEVATION MAP
Febraury 22, 2002

FORMER
EXXON SERVICE STATION 7-0277
1101 Yulupa Avenue
Santa Rosa, California

EXPLANATION

MW19 Groundwater Monitoring Well

MW14 Destroyed Groundwater Monitoring Well

AS/SVE1 Air Sparge/Vapor Extraction Well

RW2 Groundwater Recovery Well

PROJECT NO.
2101

PLATE
3